

220-901

Number: 220-901
Passing Score: 800
Time Limit: 120 min
File Version: 4.0



<http://www.gratisexam.com/>

220-901

CompTIA A+ Certification Exam

Sections

1. Hardware
2. Networking
3. Mobile Devices
4. Hardware NetTroubleshooting
5. Mix Questions

<http://www.gratisexam.com/>

Exam A

QUESTION 1

A technician needs to run a diagnostic DVD on a laptop running Windows 8.1. After setting the boot order in the UEFI BIOS to the internal DVD-RW drive, the laptop still boots into Windows. Which of the following settings needs to be adjusted in order for the laptop to boot from the DVD-RW drive?

- A. TPM
- B. Virtualization
- C. Secure boot
- D. UEFI BIOS password

Correct Answer: C

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 2

A technician is troubleshooting an expansion card in a computer that allows the computer to receive faxes over a VoIP line. The line connected to the expansion card is MOST likely which of the following cable types?

- A. Coaxial
- B. CAT3
- C. CAT6
- D. Multi-mode fiber
- E. Single-mode fiber

Correct Answer: C

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 3

For which of the following types of printers should a technician obtain a maintenance kit containing a fuser, transfer roller, and pickup rollers?

- A. Thermal

- B. Impact
- C. Inkjet
- D. Laser

Correct Answer: D
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 4

Which of the following cable connection types is an example of a mini DIN?



<http://www.gratisexam.com/>

- A. BNC
- B. PS/2
- C. RCA
- D. DB9

Correct Answer: B
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 5

A customer wants a computer for performing a single-threaded task as quickly as possible. Which of the following CPU characteristics is the MOST important?

- A. Clock speed
- B. Hyperthreading

<http://www.gratisexam.com/>

- C. Fan speed
- D. Number of cores

Correct Answer: A
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 6

Which of the following display technologies provides the BEST range of visible colors?

- A. CRT
- B. LCD
- C. Plasma
- D. OLED

Correct Answer: D
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 7

A customer wants to transfer data from the DVR to a DVD. Which of the following should be used on a workstation in order to extract the data for archiving?

- A. Optical drive
- B. Capture card
- C. Thunderbolt
- D. External storage

Correct Answer: B
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 8

A small workgroup inherits a second-hand printer without networking capabilities. Which of the following is the BEST method of sharing this resource among the workgroup?

- A. Connect the printer to a Bluetooth adapter in order for the users to print
- B. Connect the printer by using the onboard Infrared port
- C. Connect the printer to a user's workstation and share the device
- D. Connect the printer to a parallel switch box

Correct Answer: C

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 9

A technician is building a new PC and notices that it has 8 DIMM sockets labeled 0 through 7. Four are white and four are blue. Which of the following should the technician do FIRST?

- A. Install the memory in the four white slots
- B. Install the memory in the four blue slots
- C. Consult the motherboard documentation
- D. Install the memory in slots 0 through 3
- E. Fill all slots with memory

Correct Answer: C

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 10

A user wants to reduce the amount of paper consumed on a multi-function printer. Which of the following settings should be configured to achieve this outcome?

- A. Orientation
- B. Duplex

- C. Collate
- D. Economy ink

Correct Answer: B
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 11

A technician upgrades an older computer to Windows 8. The computer is running unusually slow, but the hardware has no problems and is adequate for the OS. Which of the following is the MOST likely solution?



<http://www.gratisexam.com/>

- A. Change the boot sequence
- B. Switch the BIOS to UEFI
- C. Defragment the hard drive
- D. Enable virtualization

Correct Answer: C
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 12

Which of the following types of expansion slots is MOST frequently found in blade servers?

- A. PCIe
- B. PCI

<http://www.gratisexam.com/>

- C. PCI-X
- D. miniPCI

Correct Answer: C
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 13

A user wants to extend a PC's capacity by connecting external devices. Which of the following connectors will allow the user to accomplish this? (Select TWO).

- A. eSATA
- B. IEEE 1394
- C. SATA
- D. EIDE
- E. IDE

Correct Answer: AB
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 14

Which of the following memory types is primarily used in laptops?

- A. SDRAM
- B. DDR2
- C. ECC
- D. SODIMM

Correct Answer: D
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 15

A small company needs to print several color copies of the same contract to go to various departments and customers. Which of the following printers will be the QUICKEST?

- A. 3D printing
- B. Thermal printing
- C. Impact printing
- D. Laser printing

Correct Answer: D

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 16

A computer technician is responding to a call about a printer that is causing streaks to appear on every printout. Which of the following is the MOST likely cause?

- A. Duplex unit
- B. Toner cartridge
- C. Imaging drum
- D. Pickup rollers

Correct Answer: C

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 17

Which of the following devices does a technician need to calibrate as part of an installation?

- A. Mouse
- B. Touch screen
- C. Keyboard

D. Video card

Correct Answer: B

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 18

A technician is installing Hyper-V and is getting an error that the software is not able to be installed. Which of the following processor characteristics should be checked?

- A. Cache size
- B. Virtualization support
- C. Number of cores
- D. Hyperthreading

Correct Answer: B

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 19

A technician is building a workstation that is to be used as an HTPC and will sit next to the audio receiver. Which of the following form factors would the technician MOST likely use because of its size?

- A. ATX
- B. Mini-ITX
- C. AT
- D. Micro-ATX

Correct Answer: B

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 20

A technician has connected a laptop to a television via HDMI cable. The entire display cannot be seen on the television. Which of the following settings should the technician modify?

- A. Keystone
- B. Resolution
- C. Privacy filter
- D. Frame rate

Correct Answer: B

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 21

A user is searching for a piano keyboard to connect to a PC. The user would like the keyboard to communicate with the PC. Which of the following features should the user look for on a piano keyboard to BEST facilitate this?

- A. MIDI
- B. USB
- C. TCP
- D. HDMI

Correct Answer: A

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 22

Which of the following is important when replacing a power supply in a workstation located in a datacenter server rack?

- A. A fanless power supply should be used



<http://www.gratisexam.com/>

- B. The proper voltage must be selected
- C. The unit must be the same or less wattage
- D. The power connector location must be the same

Correct Answer: B
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 23

A user opens a service ticket for a laser printer that has paper jams. Lately, jamming has become more frequent. The technician recreates the problem and checks the printer logs for more information about the printer. Which of the following choices are MOST likely fixes to this problem? (Select TWO).

- A. Clean and inspect the laser drum assembly
- B. Clean and inspect the entire paper path
- C. Use the printer maintenance kit to replace parts
- D. Replace the paper exit assembly switch
- E. Clean and replace the paper out sensor
- F. Clean the fuser cold roller and verify fuser operation

Correct Answer: BC
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 24

The technician would like to upgrade a workstation by adding a USB 3.0 card, and upgrading the video card, sound card, and NIC. The technician is concerned

about power consumption by the expansion cards. Which of the following upgrades would MOST likely require also upgrading the power supply?

- A. Video card
- B. USB 3.0 card
- C. Sound card
- D. Network card

Correct Answer: A

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 25

Which of the following protocols would be used for file sharing between MAC OS and Windows OS workstations on a LAN?

- A. IMAP
- B. SMB
- C. SSH
- D. RDP

Correct Answer: B

Section: Hardware

Explanation

Explanation/Reference:

QUESTION 26

Which of the following Internet connection types is known to have a significantly higher latency than the others?

- A. Cable
- B. Satellite
- C. DSL
- D. Fiber

Correct Answer: B

Section: Hardware
Explanation

Explanation/Reference:

QUESTION 27

Under normal circumstances, which of the following wireless standards provides the slowest transfer speed at 2.4GHz?

- A. 802.11a
- B. 802.11b
- C. 802.11g
- D. 802.11n

Correct Answer: B
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 28

An IT Director wants to increase security on the company website to prevent man-in-the-middle attacks. Which of the following Internet protocols should be implemented to meet the requirement?

- A. HTTPS
- B. IMAP
- C. TELNET
- D. SMTP

Correct Answer: A
Section: Hardware
Explanation

Explanation/Reference:

QUESTION 29

Which of the following ports is used for a secure browser connection for an online purchase?

- A. 23
- B. 80
- C. 110
- D. 443
- E. 3389

Correct Answer: D
Section: Networking
Explanation

Explanation/Reference:

QUESTION 30

Which of the following ports is typically used for sending email?

- A. 21
- B. 22
- C. 23
- D. 25

Correct Answer: D
Section: Networking
Explanation

Explanation/Reference:

QUESTION 31

Which of the following connectors are commonly used for fiber optic cables?

- A. RJ-11 and RJ-45
- B. ST and LC
- C. F-connectors
- D. BNC

Correct Answer: B

Section: Networking

Explanation

Explanation/Reference:

QUESTION 32

A machine receives an IP address starting with 169.254.x.x when which of the following occurs?

- A. When the machine is using IPv6
- B. When the next IP range begins with 169.253
- C. When the DHCP server does not respond
- D. When the operating system is Unix or Linux

Correct Answer: C

Section: Networking

Explanation

Explanation/Reference:

QUESTION 33

A technician is connecting a PoE enabled phone and needs to run the drop from the switch that is 55 meters (180.4 feet) away. Which of the following cable types would be the MOST suitable for this purpose?

- A. Fiber
- B. Coaxial
- C. CAT3
- D. CAT6

Correct Answer: D

Section: Networking

Explanation

Explanation/Reference:

QUESTION 34

Which of the following is an advantage of using DHCP for network addressing?

- A. Simplified configuration
- B. More addresses are available
- C. Faster connection speeds
- D. Lower latency times

Correct Answer: A

Section: Networking

Explanation

Explanation/Reference:

QUESTION 35

A user wants to implement a wireless router that will have the fastest data speeds and operate over the 5GHz frequency. Which of the following standards should the user select?

- A. 802.11a
- B. 802.11ac
- C. 802.11g
- D. 802.11n

Correct Answer: B

Section: Networking

Explanation

Explanation/Reference:

QUESTION 36

Which of the following devices is BEST to use when designing a SOHO network to ensure the least amount of collisions?

- A. Switch
- B. Bridge
- C. Hub
- D. Access point

Correct Answer: A

Section: Networking
Explanation

Explanation/Reference:

QUESTION 37

Which of the following Internet connection types is a digital form that runs over standard telephone wiring?

- A. Fiber
- B. Dial-up
- C. Cable
- D. DSL

Correct Answer: D
Section: Networking
Explanation

Explanation/Reference:

QUESTION 38

The device that allows two different networks to communicate with one another is:

- A. a repeater.
- B. a hub.
- C. a router.
- D. an access point.

Correct Answer: C
Section: Networking
Explanation

Explanation/Reference:

QUESTION 39

A technician is tasked with finding and labeling where a network connection terminates in a patch panel. Which of the following tools would be BEST for the technician to use?

- A. Ethernet cable tester
- B. Tone generator and probe
- C. RJ-45 loopback plug
- D. Patch panel punchdown tool

Correct Answer: B

Section: Networking

Explanation

Explanation/Reference:

QUESTION 40

A technician is tasked with replacing all the APs in an office building for greater speeds. The current location of APs allowed for total coverage of WiFi throughout the office. Which of the following 802.11 standards should be used?

- A. a
- B. ac
- C. b
- D. g
- E. n

Correct Answer: B

Section: Networking

Explanation

Explanation/Reference:

QUESTION 41

Joe, a technician, is tasked to install a new client machine. He notices the machine is not getting any network connectivity. He tests the network cable between the PC and the network jack and confirms it is good. Joe goes to the network closet and finds several network cables not connected to the switch. Which of the following tools would Joe use to determine which cable goes back to the correct network jack?

- A. Loopback plug
- B. Toner probe
- C. WiFi analyzer

D. Punchdown tool

Correct Answer: B
Section: Networking
Explanation

Explanation/Reference:

QUESTION 42

A network administrator has a requirement to implement a WiFi hotspot for the public. Which of the following should be used for secure access?

- A. WEP and TKIP
- B. WPA2 and AES
- C. WPA and static IPs
- D. WPA2 and MAC filtering

Correct Answer: B
Section: Networking
Explanation

Explanation/Reference:

QUESTION 43

Which of the following is a public IP address?

- A. 10.45.xxx.xxx
- B. 169.254.xxx.xxx
- C. 173.16.xxx.xxx
- D. 192.168.xxx.xxx

Correct Answer: C
Section: Networking
Explanation

Explanation/Reference:

QUESTION 44

A technician needs to run a cable for a new computer and the requirement is CAT6. Which of the following wiring connectors should the technician use when terminating the cable?

- A. BNC
- B. RJ-12
- C. RJ-45
- D. ST
- E. F-connector

Correct Answer: C

Section: Networking

Explanation

Explanation/Reference:

QUESTION 45

Android smartphones are typically different from other smartphone devices in that:

- A. Android devices use apps that are more secure than other devices.
- B. Android devices use open source operating systems.
- C. Android devices can only operate with a proprietary operating system.
- D. Android devices can receive apps from different sources.

Correct Answer: B

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 46

Recently a company updated their network infrastructure. A user reports that a laptop is experiencing slower network speeds since the update. Which of the following would the technician replace, rather than purchase a new device?

- A. Wireless NIC
- B. CPU
- C. RAM

D. Hard drive

Correct Answer: A

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 47

Legacy software needs to be installed on a netbook. Which of the following is MOST likely needed in order to install the software?

- A. Lightning port
- B. Bluetooth adapter
- C. USB optical drive
- D. NFC chip

Correct Answer: C

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 48

Wearable fitness tracking devices use which of the following technologies to determine user activity levels?

- A. Digitizer
- B. Gyroscope
- C. Accelerometer
- D. Inverter

Correct Answer: C

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 49

A user, Ann, is preparing to travel abroad and wants to ensure that her laptop will work properly. Which of the following components of the laptop should be verified FIRST to ensure power compatibility before traveling?

- A. Wall adapter
- B. Battery
- C. Power supply
- D. Digitizer

Correct Answer: A

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 50

A laptop is setup at a podium for a presentation but is set to extended desktop. The presenter would like it to show exactly what the laptop screen is showing. Which of the following would be the QUICKEST way to accomplish this?

- A. Look for the setting in control panel
- B. Toggle the dual display function key
- C. Change the screen orientation
- D. Reboot the laptop

Correct Answer: B

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 51

A laptop has a network port that is not working consistently and wireless is out of range. Which of the following would the technician do to quickly get the laptop back on the wired network?

- A. Use a USB to RJ-45 dongle
- B. Enable Bluetooth
- C. Enable NIC teaming

D. Replace the motherboard

Correct Answer: A

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 52

A customer wants the thinnest laptop possible. Which of the following display technologies typically allows for thinner devices?

- A. IPS
- B. OLED
- C. LCD
- D. DisplayPort

Correct Answer: B

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 53

Which of the following components is responsible for converting light into digital information?

- A. Microphone
- B. Digitizer
- C. Inverter
- D. Webcam

Correct Answer: D

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 54

A customer brings a laptop in for repair, because the screen image is upside down. Which of the following is the BEST solution?

- A. Change the screen orientation
- B. Replace the video card
- C. Connect an external monitor
- D. Update the video card drivers

Correct Answer: A

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 55

A user is requesting a cable to charge and transfer data for an Apple mobile device. Which of the following connection types would satisfy the user's requirements?

- A. MicroUSB
- B. Molex
- C. MiniUSB
- D. Lightning

Correct Answer: D

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 56

A user reports that the cursor jumps to random screen locations when typing on a laptop computer. Which of the following devices is MOST likely causing this?

- A. The touchpad
- B. The mouse wheel
- C. The multimedia keys
- D. The digitizer

Correct Answer: A
Section: Mobile Devices
Explanation

Explanation/Reference:

QUESTION 57

A user has requested a device that could be used for web-conferences while away from work. The device will mainly be used for emailing, document reviewing, and phone calls. Which of the following mobile devices would a technician MOST likely recommend?

- A. Tablet
- B. Smart camera
- C. Phablet
- D. Web camera

Correct Answer: C
Section: Mobile Devices
Explanation

Explanation/Reference:

QUESTION 58

A customer struggles with the small print of most smartphones. The customer still likes the idea of using a smartphone for phone calls and work. Which of the following devices should the technician recommend to the customer?

- A. A tablet
- B. An e-Reader
- C. A phablet
- D. A smart watch

Correct Answer: C
Section: Mobile Devices
Explanation

Explanation/Reference:

QUESTION 59

A user has downloaded an image file and needs to install an application from the image. When trying to execute or open the file, an error is displayed. Which of the following should the user perform?

- A. Download a different file from the website
- B. Rename the extension of the file to a known extension
- C. Verify the MD5 hash of the downloaded file
- D. Mount the file as an emulated DVD

Correct Answer: D

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 60

A customer asks a technician for a device that has the capability to easily connect a laptop to an external monitor, keyboard, mouse, and charge the battery. Which of the following devices should the technician recommend to the customer?

- A. Lightning
- B. KVM switch
- C. USB 3.0
- D. Docking station

Correct Answer: D

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 61

A technician is working on a laptop with a failed Ethernet port caused by ESD. Which of the following is the simplest solution to restore network connectivity?

- A. Re-solder the network connector
- B. Replace the Ethernet daughter board
- C. Update the Ethernet driver

D. Enable wireless and connect to the WAP

Correct Answer: D

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 62

When a technician is planning to replace a laptop hard drive, the technician will need to:

A. select a drive that is the correct form factor.



<http://www.gratisexam.com/>

B. choose the correct drive cache size for the laptop.

C. also upgrade the memory.

D. verify voltage requirements.

Correct Answer: A

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 63

A laptop logon screen can barely be seen, despite adjusting the display's brightness setting. Which of the following display components is defective?

A. Backlight

B. Digitizer

C. Inverter

D. Polarizer

Correct Answer: A

Section: Mobile Devices

Explanation

Explanation/Reference:

QUESTION 64

A network technician has been tasked with deploying new VoIP phones on a network. When the technician plugs the Ethernet cable for the phone into the wall port, the phone fails to turn on. When the technician plugs the Ethernet cable directly into the computer, the computer is able to access the network. Which of the following is the MOST likely cause of this issue?

- A. The network switch does not support PoE
- B. The technician is connecting the phone to the wrong type of port
- C. The firewall on the network is blocking access to the DHCP server
- D. The Ethernet cable is the wrong type

Correct Answer: A

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 65

A technician cannot communicate with one particular IP address and needs to narrow down where the traffic is stopping. Which of the following commands would be used to determine this?

- A. nslookup
- B. ipconfig
- C. nbtstat
- D. ping
- E. tracert

Correct Answer: E

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 66

A user reports that a workstation fails to complete boot up and repeats a series of two beeps over and over. The user states that the workstation had been displaying BSOD errors after running multiple applications. Which of the following is the MOST likely cause?

- A. Video adapter failure
- B. Memory failure
- C. Power supply failure
- D. CPU failure

Correct Answer: B

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 67

A technician is troubleshooting a desktop that is having intermittent issues with locking up and system errors. The technician suspects that the problem might be that not enough power is getting to the motherboard. Which of the following tools would a technician use to determine if the hypothesis is correct?

- A. POST card
- B. Loopback plug
- C. Multimeter
- D. Cable tester

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 68

A user is notified of file system errors on an external hard drive. Which of the following tools can be used to repair common errors on the drive?

- A. chkdsk

- B. diskpart
- C. format
- D. sfc

Correct Answer: A

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 69

A technician has upgraded the BIOS of a system that is running with multiple hard drives. Afterward, the system will not boot and displays an error message "Operating system not found". Which of the following is the FIRST thing the technician should inspect?

- A. The hard drive type settings in the BIOS
- B. The power supply connections to the hard drives
- C. The boot sequence settings in the BIOS
- D. The motherboard SATA connectors

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 70

An office printer that was working earlier in the day is no longer printing any documents. Pre-existing workstations are manually configured to print to the printer directly over the network. A technician has started to troubleshoot the problem and determines that the printer can still be seen in the network directory. The technician has also verified that the printer can print self-diagnostic pages successfully. Which of the following is the MOST likely cause of the problem?

- A. The printer's IP address has changed.
- B. The network print spooler service has been restarted.
- C. "Perform Printer Maintenance" message is displayed on the printer's LCD panel.
- D. Two or more users sent print jobs simultaneously, causing a print collision.

Correct Answer: A

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 71

A technician receives a call that a client's PC is not booting after a recent test of the building's back-up generators. When the technician arrives, it is discovered that, once powered on, there is no output display or POST beep codes. Furthermore, after 15 seconds, the system's fans begin running much louder and faster. Which of the following is the MOST likely issue?

- A. The motherboard was damaged by the power test.
- B. The PC's RAM was affected by ESD.
- C. The power supply was damaged and is nonfunctional.
- D. The hard drive was erased due to the power test.

Correct Answer: A

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 72

A technician receives a report from a client that is having issues with colors on a monitor. The technician notices that the monitor does not appear to have any red hues. The technician sees that the monitor has two types of inputs, VGA is currently in use, and the HDMI cable is not. The technician powers down the system and switches from using the VGA cable to the HDMI cable and the issue is resolved. Which of the following was MOST likely the issue?

- A. One of the pins on the VGA cable was damaged.
- B. The monitor did not natively support VGA input.
- C. The PC was originally configured to output to HDMI.
- D. The video card drivers were out of date.

Correct Answer: A

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 73

A client has an issue with large files taking a long time to open or save. As time goes by, the issue worsens. The client has hundreds of GBs of files that are still in the process of backing up. The technician has verified that the hard drive is healthy and there are no signs of failure. Which of the following troubleshooting steps should the technician perform NEXT?

- A. Install the latest drivers from the hardware vendor.
- B. Perform a scan of the drive for file fragmentation.
- C. Run chkdsk on the workstation's hard drive.
- D. Reformat the drive and reinstall the OS.

Correct Answer: B

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 74

A client, Ann, is having issues with a PC shutting down. There are no error messages displayed before the system powers off. Ann reports that this started after she installed and began using CAD software. The hard drive, video card, and RAM all meet the software requirements and have passed diagnostics. Which of the following is MOST likely the issue?

- A. The video card has 3D acceleration disabled.
- B. The hard drive is IDE instead of SATA.
- C. The hard drive needs to be repartitioned.
- D. The PSU is underpowered for the system.

Correct Answer: D

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 75

A printer on the second floor is not printing for anyone. However, the printer has power and displays ready on the LCD display. There is paper in the trays and the toner was recently changed. The system administrator goes to the location with a laptop and tests the network port and is able to connect. Jobs are being queued on the local machines. Which of the following should the system administrator do to get the printer functioning again?

- A. Move the printer to a known good port and connect to the network

- B. Replace the network cable to the printer
- C. Verify the server's print spooler service is running
- D. Attach the printer directly to the laptop and print a test page

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 76

The OSD of a monitor indicates the proper video source is selected, but no image is displayed. Which of the following issues are the MOST likely reasons? (Select TWO).

- A. The source cable is disconnected
- B. The monitor's brightness is set too low
- C. The backlighting of the monitor is faulty
- D. The monitor's contrast is set too high
- E. No device is sending source video

Correct Answer: AE

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 77

The loud clicking noise coming from a faulty hard drive is MOST likely created by:

- A. the coil reversing polarity in an endless loop.
- B. one or more bad spindle motor bearings.
- C. repeated motion of the read/write head armature parallel to the platter.
- D. the solid state read/write head scratching the platter surface.

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 78

A workstation has a network link light, but it cannot access internal network resources. Which of the following is the MOST likely cause of the issue?

- A. Slow transfer speeds
- B. IP address conflict
- C. Incorrect gateway
- D. Packet collisions

Correct Answer: B

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 79

Joe, a technician, is preparing to replace a laptop screen. This laptop has a touch screen to support Windows 8.1 in order to use the Metro tiles. Which of the following is the FIRST step the technician should perform?

- A. Remove the laptop bezel
- B. Document and label each cable and screw location
- C. Organize the replacement parts
- D. Refer to the manufacturer's documentation

Correct Answer: D

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 80

A user has reported that the company notebook is performing some random mouse actions requiring the user to make a lot of typing corrections. How can the technician solve the issue for the user?

- A. Adjust the mouse settings so the mouse moves slower
- B. Reverse the buttons on the mouse pad
- C. Adjust the mouse settings so the mouse moves faster
- D. Use the function keys to disable the mouse pad

Correct Answer: D

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 81

A network printer is online and ready. The accounting group is unable to print to this network printer, but other departments can. Which of the following would the technician use to resolve the problem?

- A. Replace the printer's network cable
- B. Modify the security setting of the print spooler
- C. Restart the TCP/IP print spooler service
- D. Use the manufacturer's maintenance kit

Correct Answer: B

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 82

A customer has left a computer monitor on over the weekend and now notices slight discoloration of the screen. This is an example of:

- A. a failing backlight.
- B. burn in.
- C. a bad inverter.
- D. dead pixels.
- E. EMI.

Correct Answer: B

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 83

A user, Ann, reports that her company laptop cannot pick up a wireless connection in certain areas of a building. However, users working on their laptops in the common areas have Internet connectivity. Which of the following is the MOST likely cause?

- A. Weak RF signals
- B. Out of date Ethernet driver
- C. Enabled MAC filtering
- D. Duplicate IP addresses

Correct Answer: A

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 84

After receiving a call from an executive, a technician walks into a meeting room to find that the projector is not showing the screen of the executive's laptop. The projector shows a message that reads "No video signal". Which of the following is the FIRST thing that the technician should do?

- A. Adjust the laptop's screen brightness
- B. Replace the projector's bulb
- C. Verify the VGA cable is connected
- D. Ensure secondary display is enabled

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 85

A user states there are multiple small black dots on an LCD screen. Which of the following should be done to resolve the issue?

- A. Replace monitor.
- B. Replace video card.
- C. Replace video cable.
- D. Replace power supply.

Correct Answer: A

Section: Hardware NetTroublshooting

Explanation

Explanation/Reference:

QUESTION 86

A client's computer is not connecting to a website. Which of the following commands will allow the technician to view the route/number of hops between the host and remote systems?

- A. nbtstat
- B. tracert
- C. nslookup
- D. netstat

Correct Answer: B

Section: Hardware NetTroublshooting

Explanation

Explanation/Reference:

QUESTION 87

A user is trying to use an external hard drive with an incompatible file system. Which of the following tools will allow the user to change the file system on the hard drive?

- A. format
- B. defrag
- C. bootrec

D. chkdsk

Correct Answer: A

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 88

A brownout has occurred within a building. A technician is repairing a workstation which has a power light, but is not displaying anything on the screen and is not making any sounds during boot up. Which of the following should be used to further troubleshoot the workstation?

- A. Loop back plug
- B. POST card
- C. Power supply tester
- D. Multimeter

Correct Answer: B

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 89

A user is reporting that a desktop monitor backlighting is very dim. Which of the following should be performed FIRST when troubleshooting the problem?

- A. Update drivers
- B. Reseat the video card
- C. Use OSD tools
- D. Replace the monitor

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 90

A user reports that the mouse is not working properly. The technician notices on the user's workstation that the mouse cursor spins for several minutes before the technician can use the mouse. Which of the following is the cause of the issue?

- A. Failed Operating System
- B. Faulty mouse
- C. Faulty CPU
- D. Not enough memory

Correct Answer: D

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 91

A technician replaces a failed hard drive with a brand new one. The technician boots from a PE CD and attempts to install a custom OS build deployed from the network. The hard drive is visible in the system's BIOS. However, once in the preinstallation environment, the drive is not recognized in the imaging process and the process fails. Which of the following is MOST likely the cause of failure?

- A. The boot CD has failed and needs to be replaced.
- B. The hard drive needs to have its configuration manually defined in the BIOS.
- C. The PC's power supply is not providing enough power to the new hard drive.
- D. The hard drive has not been partitioned correctly.

Correct Answer: D

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 92

A technician is notified that a laptop is not booting. It is discovered that there are no system lights, sounds, or display when the power button is pressed. Which of the following should the technician attempt FIRST in the troubleshooting process?

- A. Connect an external monitor into the laptop to determine if the LCD has failed.

- B. Boot the system from either a boot CD or other removable media type.
- C. Disconnect the AC and battery power and hold the power button for several seconds.
- D. Remove any hard drives or optical drives, RAM, and any wireless cards or USB devices from the laptop.

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 93

A user attempts to turn on a computer and receives no response. The user calls the technician to report the computer is not booting and a faint smell of something burning. Which of the following tools will BEST help to identify the issue?

- A. ESD strap
- B. PSU tester
- C. Cable tester
- D. Loopback plug

Correct Answer: B

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 94

A user notices the printer that is used for printing global shipper's labels is missing columns in the printed labels. The special label stock is new and appears to be fine. Which of the following should the technician perform FIRST when troubleshooting this problem?

- A. Remove any stuck labels from the paper path
- B. Clean the pickup rollers and check them for wear
- C. Clean the print head with approved materials
- D. Replace and realign the print head

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 95

Ann, a user, reports her docked mobile workstation will periodically lose her network share drive and lose video to the second monitor. Which of the following is MOST likely the cause of this anomaly?

- A. The workstation battery needs to be replaced.
- B. The NIC is functioning intermittently.
- C. Failed driver updates for the workstation's devices.
- D. The surge protector lost AC power.

Correct Answer: D

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 96

A user reports an inkjet printer is constantly feeding two sheets of paper for every page printed. Which of the following is the MOST likely reason?

- A. Poor paper quality
- B. Incorrect paper size
- C. Defective duplexer
- D. Worn feed rollers

Correct Answer: D

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 97

A technician is working on a server with high latency on the mapped network drive. Upon entry into the server room, the technician suspects an issue with one of the drives in the array. Which of the following would the technician do to resolve the problem?

- A. Reseat the drive cable in the array.
- B. Replace the RAID controller.
- C. Replace the faulty drive in the array.
- D. Reinstall the RAID drivers.

Correct Answer: C

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 98

Joe, a user, receives a wireless router from his ISP with a pre-set password and configuration. He can connect to the router fine via Ethernet but cannot see the wireless signal on any of his devices. The LEDs on the router indicate that a wireless signal is broadcasting. Which of the following settings on the router does Joe need to adjust to enable the devices to see the wireless signal?

- A. DHCP
- B. IPv6
- C. DMZ
- D. SSID

Correct Answer: D

Section: Hardware NetTroubleshooting

Explanation

Explanation/Reference:

QUESTION 99

A technician is tasked with upgrading the hard drives of a high-end workstation to SSD. The drives must be configured in a RAID array, but the RAID card does not support SSD. Which of the following would the technician verify in order to use the new drives?

- A. Controller firmware
- B. Power requirements
- C. File system type
- D. System BIOS

Correct Answer: A

Section: Hardware NetTroublshooting

Explanation

Explanation/Reference:

QUESTION 100

A customer states that when booting up the workstation, there is a message that says “no operating system detected”; then, it continues to boot into the operating system. The customer is preparing to modify files on a USB drive. Which of the following should a technician perform to resolve the problem?

- A. Reinstall the operating system to reinstall the hardware drivers.
- B. Modify the boot.ini within the operating system.
- C. Modify the boot sequence within the UEFI.
- D. Disable the TPM chip to turn off data encryption.

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 101

A customer signed up for the mobile pay service to use with their first generation smartphone but it does not work at any place that supports the mobile pay service. Which of the following is missing from the customer’s smartphone?

- A. RFID
- B. IMSI
- C. NFC chip
- D. Bluetooth

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 102

A user wants to store a personal video to view at a later time. Which of the following types of media is the LEAST expensive with a maximum capacity of 750MB?

- A. USB drive
- B. DVD-R
- C. Blu-Ray
- D. CD-R

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 103

A technician is building a workstation that will only be used to connect remotely to a server. Which of the following types of PC configurations is BEST suited for this task?

- A. Thin client
- B. Home server PC
- C. CAD workstation
- D. AV workstation

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 104

A user is watching streaming video on a home network, but experiences buffering and delays when there are too many people on the network. Which of the following is MOST likely to resolve the issue?



<http://www.gratisexam.com/>

- A. Disable SSID broadcast
- B. Setup UPnP
- C. Enable QoS
- D. Configure DMZ

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 105

A small office would like to offer Internet access to customers while onsite. However, customers should not be able to access any corporate data. Which of the following networking features would BEST enable this?

- A. Configure a guest wireless network
- B. Implement a DMZ
- C. Disable NAT on the wireless network
- D. Disable the SSID
- E. Assign static IPs for all devices

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 106

<http://www.gratisexam.com/>

Which of the following types of media connectors carries digital video as well as audio?

- A. DVI-D
- B. DVI-A
- C. HDMI
- D. VGA

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 107

Which of the following is a type of fiber connector?

- A. RJ-11
- B. F-connector
- C. BNC
- D. ST

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 108

Which of the following ports is used when accessing a website with SSL encryption?

- A. 22
- B. 80
- C. 110
- D. 443

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 109

Two drives in a RAID 5 have failed. Which of the following will the technician need to implement?

- A. Replace the failed drives and restore the data from backup to the RAID.
- B. Replace one of the failed drives and run the RAID repair.
- C. Replace the failed drives and format the RAID using the quick option.
- D. Replace one of the failed drives and repair the RAID using system utilities.

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 110

A user is unable to show an Android smartphone display on a TV. Which of the following settings should the technician check to resolve this issue?

- A. Multi-window
- B. Air view
- C. Air browse
- D. Screen mirroring

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 111

A network technician connects a tone generator to an RJ-45 drop. Which of the following is the MOST likely reason for doing this?

- A. To validate proper wiring of the network jack
- B. To confirm continuity of the conductors
- C. To locate the position of the cable on a patch panel
- D. To test the transmission quality of the connection

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 112

A SOHO is considering a purchase of several printers that will facilitate printing on both sides of the media. Which of the following optional add-ons will provide this functionality?

- A. Collate
- B. Duplex
- C. Fast draft
- D. Paper type

Correct Answer: B

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 113

A group of users need to connect directly to a printer with continuous access. Which of the following connection types will achieve this?

- A. Serial
- B. Ethernet
- C. USB
- D. eSATA

Correct Answer: B

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 114

A PC has been randomly rebooting several times a day. The technician checks the case for overheating and finds the fans appear to be operating normally. Which of the following should the technician check NEXT?

- A. The motherboard for any sign of swollen capacitors
- B. The disk drive to determine if it is defragmented and operating properly
- C. The embedded NIC to ensure it has the latest firmware and drivers
- D. The RAM to confirm it is the correct type for the motherboard being used

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 115

A user is reporting toner smudging on paper after printing. Which of the following should the technician inspect?

- A. Print spooler
- B. Fuser
- C. Rollers
- D. Maintenance kit

Correct Answer: B

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 116

A new employee has reported that print jobs are printing as garbled text. Which of the following is MOST likely the reason for this issue?

- A. The printer needs a maintenance kit installed
- B. The network cable on the printer is unplugged
- C. The workstation has the incorrect drivers installed
- D. The employee does not have the proper permissions

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 117

A customer is reporting that after removing a laptop from the docking station and bringing it home, the cursor occasionally jumps around the screen while the customer is typing. Which of the following should the technician do to mitigate this issue?

- A. Disable the touch pad on the laptop
- B. Install new keyboard drivers for the laptop
- C. Install new drivers for the docking station
- D. Disable the keyboard on the laptop

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 118

Ann, a user, wants to host a gaming server on her SOHO network. Which of the following features on the SOHO router would need to be configured?

- A. Channels
- B. DHCP
- C. Port forwarding
- D. Firmware

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 119

Ann, a user, boots her laptop and notices the screen flashes then turns black. It was working during her presentation yesterday. Which of the following troubleshooting steps should be completed?

- A. Use a multimeter to test voltage.
- B. Replace the laptop with a new one.
- C. Replace the battery.
- D. Connect an external display device.

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 120

A customer wants to connect a laptop to a mobile device's Internet for use in situations where there is no Internet connectivity. Which of the following technologies would the technician recommend to the customer?

- A. IR
- B. NFC
- C. Hotspot
- D. Lightning

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 121

A technician is asked to install Microsoft office directly on a customer's computing device. The technician notifies the customer that office cannot be installed directly on that device. Which of the following device types does the customer have?

- A. Mac
- B. Thick client
- C. Thin client
- D. Phablet

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 122

Which of the following wireless technologies is LEAST likely to be intercepted by a third party?

- A. NFC
- B. Bluetooth
- C. WiFi
- D. Cellular

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 123

A user works in a public kiosk where their laptop is susceptible to theft. The information can be remotely wiped so data loss is not a concern. Which of the following options should be considered to secure the laptop?

- A. Use data encryption.
- B. Use a cable lock.
- C. Use multifactor authentication.
- D. Use a strong password.

Correct Answer: B

Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 124

A user is noticing fine black particles on printouts and in the printer itself. Which of the following tools is recommended to fix this issue?

- A. Denatured alcohol
- B. Toner vacuum
- C. Compressed air
- D. Moist towel

Correct Answer: B

Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 125

A technician finds an external hard drive with the markings "IEEE 1394" on it. Which of the following cable types would be needed to view the contents of this drive?

- A. Ethernet
- B. eSATA
- C. FireWire
- D. MicroUSB

Correct Answer: C

Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 126

A user creates a file in presentation software to be shown on a widescreen display. The user would like to adjust the aspect ratio of the slides in the presentation software so they display without extra black areas on the top, bottom, left, or right of the slides. Which of the following aspect ratios would BEST meet this

requirement?

- A. 4:3
- B. 5:4
- C. 16:9
- D. 256:135

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 127

The technician is troubleshooting a connection issue between the switch and the wall jack. The user is plugged into the jack; however, there is no connection. The technician goes into the switch room to see if the cable is plugged into the switch, but none of the cables are labeled. Which of the following tools would the technician MOST likely use to find this cable?

- A. WiFi analyzer
- B. Loopback plug
- C. Multimeter
- D. Tone generator

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 128

A technician is required to connect a new cable to an open port on the patch panel. Which of the following would the technician MOST likely use in this situation?

- A. Loopback tool
- B. Multimeter
- C. Punchdown tool
- D. Toner probe

Correct Answer: C
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 129

Which of the following would typically require the use of a punchdown tool to connect a cable to the network switch?

- A. Router
- B. Repeater
- C. Patch panel
- D. PoE injector

Correct Answer: C
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 130

A technician is notified of an inkjet printer not printing properly. The user's computer has the printer software loaded and is not displaying any errors. A test print was performed, with one of the colors not printing properly. Which of the following would the technician typically perform FIRST to resolve the issue?

- A. Replace cartridges
- B. Run a cleaning page
- C. Clean heads
- D. Clean fuser assembly

Correct Answer: C
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 131

A technician is tasked with setting up a workstation in a new location. The technician realizes there is no network connectivity and the workstation's NIC does not have a link light. Given the connection in the wall is correctly labeled, which of the following would be BEST for the technician to use NEXT?

- A. A multimeter
- B. A tone generator
- C. A cable tester
- D. A punchdown tool

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 132

A technician is responsible for setting up laptops in a room for a small conference. The laptops need to communicate with each other as well as a workstation in the room. The workstation has a wireless expansion card. A switch is not available for the laptops and they cannot access the corporate network. Which of the following does the technician need to implement?

- A. Adhoc network
- B. Bluetooth network
- C. Serial network
- D. USB network

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 133

A technician is planning on running multimode fiber and only needs the fiber runs to be 500 feet (152 meters) in distance. Which of the following connectors should the technician use?

- A. BNC
- B. LC
- C. ST

D. F

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 134

A user wants pages 1-5 separated from 6-8 when they are retrieved from the printer. Which of the following settings would the user change in the print job to ensure the pages are separated?

- A. Duplex
- B. Collate
- C. Orientation
- D. Quality

Correct Answer: B

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 135

A video projector shows the image from a laptop, but everything is colored blue. Which of the following is the MOST likely the cause?

- A. Dead pixels
- B. Video resolution
- C. Failing lamp
- D. VGA connection

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 136

A new company is thinking of upgrading its media workstation in the conference room. The computer will be predominantly used for graphically intensive presentations, slideshows, and video gaming tournaments. Which of the following BEST satisfies the needs of the company?

- A. High-end video, high-end audio, multicore processor
- B. Minimum RAM required, network connectivity, high-end cooling
- C. Media streaming, file sharing, gigabit NIC, dual monitors, TV tuner
- D. Network connectivity, TV tuner, surround sound audio, dual monitors

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 137

Which of the following would likely be the MOST cost-effective media to use for storing 8GB of data?

- A. DVD RW
- B. CD-ROM
- C. Tape backup
- D. DVD+R DL

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 138

Which of the following is an advantage of using static IP addresses for a business?

- A. High availability
- B. Simplifies IP management
- C. Lower security risk
- D. Scalability for upgrades

Correct Answer: A
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 139

Which of the following is an advantage of UDP over TCP?

- A. It is connection based.
- B. It uses flow control.
- C. It transfers packets faster.
- D. It uses connection handshakes.

Correct Answer: C
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 140

A technician has just installed a wireless access point in a customer's home office. While testing the network and browsing the Internet, the technician finds that the connection is not stable, speeds are slow, and websites sometimes do not load. Which of the following should the technician do FIRST?

- A. Re-enable the broadcasting of the access point's SSID so it is visible to mobile devices.
- B. Use a WiFi analyzer to ensure neighboring networks are not using the same channel.
- C. Reconfigure network devices to use static IPs instead of DHCP-assigned addresses.
- D. Change the signal encryption from WPA2 to WEP to ease transmission overhead.

Correct Answer: B
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 141

Which of the following features is an advantage of a switch over a hub?

- A. A switch routes packets instead of frames to different networks.
- B. A switch divides bandwidth among connected devices.
- C. A switch broadcasts the data frames to every connected device.
- D. A switch sends data frames to the correct connected device.

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 142

Which of the following is used to facilitate communications with a user's smartphone in order to make purchases and payments by proximity?

- A. Bluetooth
- B. IR
- C. NFC
- D. WPS

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 143

A technician needs to boot a PC from a USB drive. Which of the following settings should be disabled to accomplish this task?

- A. Fast Boot
- B. UEFI Admin Password
- C. Secure Boot
- D. Legacy Boot

Correct Answer: C
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 144

Which of the following connectors can be used for video, audio, and storage devices?

- A. DVI
- B. DisplayPort
- C. HDMI
- D. Thunderbolt

Correct Answer: D
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 145

A company wants to conserve paper without limiting the ability to print. Which of the following settings needs to be configured?

- A. Orientation
- B. Duplex
- C. Collate
- D. Quality

Correct Answer: B
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 146

Which of the following network devices filters traffic of many different protocols based on a predetermined set of rules established by a system administrator?

- A. Proxy
- B. Switch
- C. Firewall
- D. Router

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 147

An IT manager needs to install a large display in a front office area with a lot of natural light. Which of the following display technologies will BEST satisfy the requirements of the design plan?

- A. CRT
- B. CCFL LCD
- C. IPS LCD
- D. LED LCD

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 148

An employee wants to work more efficiently from home. The IT manager suggests the employee consider purchasing a device that will allow use of monitor and input devices with the work laptop. Which of the following devices is MOST suitable for this purpose?

- A. Docking station
- B. Set-top box
- C. KVM switch
- D. USB hub

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 149

A technician is installing a network-enabled security system that features IP-based cameras. To access the system remotely, which of the following capabilities is MOST likely to require configuration?

- A. VPN passthrough
- B. QoS
- C. Static IPs
- D. Port forwarding

Correct Answer: D

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 150

Which of the following devices is primarily intended to provide 24/7 diagnostic and biometric data regarding the user?

- A. Fitness monitor
- B. e-Reader
- C. Smartwatch
- D. Smartphone

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 151

A user has received an error message when connecting to the wireless network. The error indicates the IP address being used by the user's system is already in

use. A DHCP server is used on the network. After having the user disconnect from the wireless network, the technician is still able to ping the user's IP address. Which of the following is MOST likely the cause?

- A. The user has a statically assigned IP address in the DHCP server scope.
- B. The system's local firewall is blocking SYN/ACK traffic from the DHCP server.
- C. The DHCP server's scope has been exhausted and no additional IP addresses are available.
- D. The user is also connected to the wired network with a LAN cable.

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 152

After migrating a network-based print queue to a new server, users are reporting that documents are not printing correctly and print jobs will error out or print garbled text. Which of the following actions will BEST resolve this issue for the affected users?

- A. Install the correct drivers on the server.
- B. Delete and reconnect to the print queue on the client machine.
- C. Restart the print queues on the print server.
- D. Reinstall the printer drivers on the client desktops.

Correct Answer: A

Section: Mix Questions

Explanation

Explanation/Reference:

QUESTION 153

The Chief Executive Officer (CEO) of a company has requested outside access to a server within the company network so that sensitive documents can be worked on from home. Which of the following is the MOST appropriate tool to give the CEO the requested access?

- A. VNC
- B. Port forwarding
- C. Port triggering
- D. VPN

Correct Answer: D
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 154

A user reports the cursor jumps around when typing in documents on a new laptop. Which of the following is MOST likely causing the issue?

- A. Touchpad settings
- B. Screen calibration
- C. Incompatible software
- D. Unsigned hardware

Correct Answer: A
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 155

A technician needs to set up a VPN for a small office. To ensure the network traffic is routed to the correct machine, which of the following MUST the technician do on the router to accommodate this?

- A. Port forwarding
- B. Port redundancy
- C. Port triggering
- D. Port selection

Correct Answer: A
Section: Mix Questions
Explanation

Explanation/Reference:

QUESTION 156

Users have started calling the helpdesk reporting they cannot access resources on the network or the Internet. A technician has verified all hardware connections are operational. Which of the following settings should the technician check NEXT on the router?

- A. SNMP
- B. NNTP
- C. DHCP
- D. WLAN

Correct Answer: C

Section: Mix Questions

Explanation

Explanation/Reference:



<http://www.gratisexam.com/>